

# General Environmental Incident Summary

**Incident:** 5220      **Date/Time Notice:** 9/8/2016      0955      **DEM Incident No:**

**Responsible Party:** TDS Trucking

**Date Incident:** 9/8/2016      **Time Incident:** 0710      **Duration:**

**County:** Burleigh      **Twp:** 142      **Rng:** 80      **Sec:** 10      **Qtr:**

**Lat:** 47.14244      **Long:** -100.79220      **Method:** Interpolation from map

**Location Description:** On the corner of north bound hwy 83 and hwy 36 Wilton, ND

**Submitted By:** Kevin Miller

**Affiliation:**

**Address:** 515 N Mill St

**City:** Fertile

**State:** MN

**Zip:** 56540

**Received By:**

**Contact Person:** Kevin Miller  
515 N Mill St  
Fertile, MN 56540

**Distance Nearest Occupied Building:** 400 Feet

**Release Contained:** Yes

**Type of Incident:** Vehicle Accident

**Description of Released Contaminant:** #2 clear diesel

**Volume Spilled:**

**Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Reported to NRC:** Unknown

**Cause of Incident:**

Semi tractor/trailer roll over rupturing driver side fuel tank

**Risk Evaluation:**

Soil with diesel fuel mix

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

Diesel spilled on road way and flowed to the edge of the road.

**Action Taken or Planned:**

Spill report, contact ND Dot, locate company to clean up area

**Wastes Disposal Location:**

**Agencies Involved:** NDDes, State Highway Patrol, Local Law Enforcement

## **Updates**

---

**Date:** 9/8/2016    **Status:** Reviewed - Follow-up Required

**Author:** Martin, Russell

### **Updated Volume:**

#### **Notes:**

Phone call with county sheriff on site and follow-up with responsible party. Sheriff's estimate is 130 gallons of diesel from passenger side saddle tank impacted roadway and shoulder slope. Some standing water is in the shoulder ditch; however, it is about 70 yards away from the spill. Responsible party looking for contractor to remove impacted soil after contacting NDDOT about any requirements it may have for the cleanup since it might affect the roadway.

---

**Date:** 10/11/2016    **Status:** Awaiting Documentation

**Author:** Martin, Russell

### **Updated Volume:**

#### **Notes:**

Correspondence from responsible party on cleanup of the site: "The cleanup went well from what I have heard. Pinnacle Engineering of Minneapolis was handling the cleanup. I spoke to them a week or two ago to get an update. They took what they guessed at about 60 yards they pulled up and hauled away. They put down an enzyme I believe to help break up the fuel. They took samples and were awaiting the results and NDDOT's approval if anything else was needed. Hefty Seed of Wilton was going to fill and lay grass seed once they got the approval from the state. I have not received any paperwork from Pinnacle for the cleanup due to waiting on final approval. If there's anything else I can help you with please let me know."